



Town Belmont
Historic District Commission
 Homer Municipal Building, 2nd Floor
 19 Moore Street
 Belmont, MA 02478

OFFICE USE
Case Number: HDC -

APPLICATION

In accordance with the Historic Districts Act, MGL Ch 40C, and the Town of Belmont General Bylaws, §40-315, the undersigned applies to the Belmont Historic District Commission for a Certificate of:

- Appropriateness Non-Applicability Hardship

1. PRELIMINARY INFORMATION:

Address of Property: 644 Pleasant st.
 Property Owner's Name: Town of Belmont
 Address: 644 Pleasant st
 Email: _____ Phone: _____
 Agent Name: Blusky Restorations
 Address: 6 Commerce Center MA 02330
 Email: mike.Raskin@boblusky.com Phone: 774-260-7113
 I am the : _____ Property Owner Agent
 _____ Property is Owned by a Corporation, LLC, or Trust (Submit authorization to sign as owner)
 _____ Property is a Condominium or Cooperative Association (submit authorization to sign as trustee)
 If applicable: Architect: _____ Contractor: _____

2. BRIEF DESCRIPTION OF PROPOSED WORK:

Repair of Front handrail and tile mosaic at Landing in front of Building. Using Original Railing, cleaned + repainted. Best Match @ mosaic.

3. SIGNATURES:

As Owner, I make the following representations:

- A. I hereby certify that I am the Owner of the Property at: _____
 B. I hereby certify that if an Agent is listed on this Application, this Agent has been authorized to represent this Application before the Belmont Historic District Commission.

Owner: [Signature] Date: 5/2/2022

As Applicant/Agent, I make the following representations:

1. The information supplied on and in this Application is accurate to the best of my knowledge;
 2. I will make no changes to the approved plans without prior approval from the Belmont Historic District Commission.

Applicant/Agent: [Signature] Date: 4/20/22

* Incomplete applications and Insufficient documentation will not be accepted. *

Approved March 23, 2017

Application Statement for Belmont Historical Commission:

This is an application to repair the damage to the front steps of the Belmont School Administrative building due to a vehicle strike. The repair will consist of replacing the existing granite steps and repairing the front portion of the tile mosaic. Tile samples have been provided.



